

5912881219

Vitastíg 1 Bolungarvík

Heilbrigðiseftirlit Vestfjarða

Matís Ohf **Microbiological analysis** Vínlandsleið 12 113 Reykjavík Phone: (354)-422 5000 Fax:(354)-422 5001



LABORATORY REPORT Issued by Accredited laboratory NYSDOH LAB ID 11290

Page 1 of 1

Sample No. R18027640001 Water

Sample Date: Recieved: Analysed:

18/10/2018 19/10/2018 19/10/2018

Sample Location	:	Reykhólahreppi 1-Þör/Þörungaverksmiðjan, Reykhólum Sample fulfils Icelandic drinking water regulation no.		
Microbiological Analysis		Result	Reference	
E.coli in 100 ml MF (ÖVA3)		0	ISO 9308-1:1990 & ISO 9308-1:2000	
Total count in 1 ml at 22°C (ÖVA5)		3	SM, 23. ed.2017, 9215B & ISO 6222:1999 mod.	
Coliforms in 100 ml (ÖVA3) MF		0	ISO 9308-1:1990 & ISO 9308-1:2000	
Chemical and Physical Analysis		Result	Reference	
**Acidity (pH) (EVA1)		7,30	ISO 10523:2012	
**Ammonia, NH4-N(EVA6)		<0,05mg/L	HACH, DR/2000 SP	
**Turbidity		<0,10NTU	IST EN ISO 7027:1999	
**Conductivity (EVA3)		110µS/cm	ISO 7888:2012	

Reykjavík,

22.10.2018

This laboratory report is approved and digitally signed:

Páll Steinþórsson pall.steinthorsson@matis.is

** Not accredited results

The results refer only to the sample analysed. Laboratories are accredited by the Swedish Board for Accreditation and Conformity Assessment (SWEDAC) under the terms of Swedish legislation. The accredited laboratory activities meet the requirements of the ISO/IEC 17025 standard. This test report/certificate may only be reproduced in whole, otherwise a written permission from Matis is required. The laboratory meets the demands of the NELAC standard of New York State Department of Health (NYSDOH), NY Lab Id No: 11290 Information about uncertainty of the analysis can be sought upon request by contacting the laboratory. Calculation of uncertainty is done with a coverage factor of 2 and gives a confidence level of approximately 95%.

For further information, please contact the person signing the report or Margrét Geirsdóttir Quality manager.